
Rear View Front View 66 XX 67 Add-ons Loose/broken/delaminated Missing Previous repair Spindles not original to desk Damage/wear/hole Replaced piece Inscriptions


Right Side Loose/broken/delaminated Previous repair Damage/wear/hole Replaced piece

Add-ons Missing Spindles not original to desk Inscriptions


Left Side

Тор












Bottom


Bottom





Drawer Front, Outer Surface


Rear Surface of Drawer Front















Inside Surface of Left Drawer Side


Inside Surface of Right Drawer Side





Rear Surface of Drawer Back


Front Surface of Drawer Back














Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side

